

## County of Riverside DEPARTMENT OF ENVIRONMENTAL HEALTH

For general information call: 1-888-722-4234 www.rivcoeh.org

FACILITY NAME						DATE	TIME IN	TIME OUT
Kentucky Fried Chicken					10/10/2019	9:00 AM	TIME OUT 11:00 AM	
						RE-INSPECTION DATE		
81769 Hwy. 111, Indio, CA 92201						Next Routine		
PERMIT HOLDER					E-MAIL			
						Not Specified		
PERMIT#	EXPIRATION DATE:	SERVICE	FACILITY PHONE	PE	DISTRICT	INSPECTOR NAME	7.	
PR0057865	12/31/2019	Inspection or followup with no score given	(310)691-3423	3621	0038	Jaclyn Hickey		

## Inspector Observations:

Re-inspection was conducted by J. Hickey, D. Covos, Y. Monroy, and T. Skrove in response to a complaint CO#0070898. Spoke with April Holgiun, the area leader and Crystal the manager of the facility. The following was discussed:

- -Spoke with Valley Sanitary District, sample box was open, observed grease interceptor to be almost full.
- -Observed street to be cleaned. As per Valley Sanitary, the Valley Sanitary department responded and cleaned the overflow.
- -Observed area surrounding the grease interceptor cover and sample box to be completely saturated. Clean and disinfect the area surrounding the grease interceptor.
- -Observed food debris and grease attached to walls of the grease line cleanout. Recommend servicing lines to ensure proper cleaning of lines. Consult a certified plumber for recommendations.
- -Toilet paper debris around the sewer cap near front door. Properly clean and sanitize the area.
- -Observed cleanout closest to the street to be dry, potential issue in system before this cleanout.
- -As per operator, grease interceptor is serviced/pumped every 6 weeks by company SLM.
- -Valley Sanitary district will conduct tests to ensure proper function of the grease interceptor.
- -Action plan/SOP will be required to be sent to this department about proper best practice procedures. Discussed best management practices for proper operation and for reducing food debris flowing into the drain lines. Provide procedures of facility measures if another overflow occurs.
- -Create visual logs to ensure grease interceptor is functioning properly and not overflowing. Visual inspections shall be logged every 30 minutes. Provide copies of logs daily until additional assessment can be made on the grease interceptor.
- -Valley Sanitary District observed sewer system to be functioning at this time.
- -Contact City of Indio if grease interceptor overflows again, and immediately cease and desist operation.
- -Ensure no food preparation is being done until facility has been properly sanitized and cleared for opening. Ensure any and all food that has been or has the potential to be contaminated is properly discarded.
- -Facility is not approved to operate at this time. Pending approvals from all other agencies and correction of the above stated facility is conditionally approved.
- -Provide all documentation and photographs to this department of work conducted.
- -If another overflow/back up occurs facility will be closed indefinitely until grease interceptor and piping is assessed and repaired.
- -An office hearing is scheduled for tomorrow 10/11/19 at 3:00 pm at 47950 Arabia St, Ste A, Indio, CA 92201.

Signature		_				
Ammy	Jaclyn Fickery					
April Holguin	Jaclyn Hickey Environmental Health Specialist					
Person in Charge						
10/10/2019	10/10/2019					